

Special Calibration Considerations:

Hydrogen Sulfide Sensor (PN° 823-0206-21)

Zeroing The Sensor

There are no special zeroing considerations for this sensor. Complete zeroing instructions are provided in Section 3.1 of the SensAlert^{Plus} User Manual or SensAlert ASI User Manual.

Span Calibration

It is recommended that this sensor be calibrated at the half-scale concentration of 50 ppm. There are no special calibration considerations for this sensor. Complete span calibration instructions are provided in Section 3.2 of the SensAlert^{Plus} User Manual or SensAlert ASI User Manual.

Test-on-Demand Cell

Test-On-Demand cell available for this sensor: 821-0204-06 (Type S)